2615 20th Ave Fairbanks, AK 99709 (907) 931-8808



Number Est. Date
1537494 08/07/2025

Est. Created By
Dan Kimmel
Location Customer PO
FBX

		Lanca de la constante de la co	Name and Address of the Owner, where the Owner, which the Owner, where the Owner, which the
ENDER STATE OF THE	BIII To	Machine	INDUSTRIES.
CITY OF DELTA JUNCTION [440074] P O BOX 229 DELTA JUNCTION, AK 99737		Stock #: RT1554 Make/Model: VOLVO L220F S/N: L220FT00008248 Sold on 2/28/2011 Description: VOLVO L220F LOADER Total hours as of 08/07/2025: 38077.00	
THE REPORT OF THE PARTY OF THE	WERE COMPANY OF THE PARTY OF TH	Notes	
REV/CITY of DELTA RT155 LOCATION: CMI SHOP	54 - HYD OIL OVERFILLING TRANSMISS	BION	
		Jobs	
Customer Approval Yes No	Associated with the make and model of the commencing any work the technician will	must have a copy of the Service Manual the equipment to be worked on, Prior to thave read and understood safety by manufacturer for the tasks associated	Parts: \$ 0.00 Labor: \$ 0.00 Subtotal: \$ 0.00
Customer Approval	01 - WASH MACHINE		Estimated Cost
Yes No	Complaint CUSTOMER STATES HYD FLUID IS O' FILLING THE ENGINE Cause No cause has been found for this job.	VERFILLING THE TRANSMISSION &	Parts: \$ 0.00 Labor: \$ 975.00 Subtotal: \$ 975.00
Customer Approval	02 - FRAIN FLUIDS		Estimated Cost
☐ Yes ☐ No	Complaint 02 - CHANGE FILTERS, DRAIN & REF! - ENGINE OIL - TRANSMISSION OIL	LL FLUIDS	Parts: \$ 3,585.51 Labor: \$ 585.00 Subtotal: \$ 4,170.51
	- HYDRAULIC OIL Cause No cause has been found for this job. Parts		

2615 20th Ave Fairbanks, AK 99709 (907) 931-8808



Estimate

Number Est. Date

1537494 08/07/2025

Est. Created By

Dan Kimmel

Location Customer PO

FBX

	Part No.	Description	Qty	List	Ext		
	17533661	OIL FILTER	2.00	32.14	64.28		
	Oil & Grease	HYD. OIL 70 GAL	1.00	2,284.80	2,284.80		
	11172907	AIR FILTER	1.00	42.59	42.59		
	11038369	GASKET	1.00	19.36	19.36		
	17418113	FILTER CARTRIDGE	1.00	144.31	144.31		
	21707132	OIL FILTER	1.00	32.14	32.14		
	Oil & Grease	AT102 15 GAL	1.00	559.204	559.20		
	Oil & Grease	15-40 12 GAL	1.00	268,68	268.68		
	11707077	FILTER INSERT	1.00	33.69	33.69		
	17438620	FILTER ELEMENT	1.00	A36.46	136.46		
Customer Approval	03 - REMO	VE AND INSTALL CAB		4		Estimate	d Cost
	Complaint		di			Parts:	\$ 0.00
☐ Yes ☐ No		AND INSTALL CAB	A Carrie			Labor:	\$ 2,340.00
	Cause		ast.			Subtotal:	\$ 2,340.00
	No cause has b	een found for this job.	/				
			A 1 11 10	TANK		Estimate	d Cost
Customer Approval	04 - REMO	VE AND INSTALL HYDR	AULIC	IANK		Parts:	\$ 0.00
	Complaint	<i>f</i>				Labor:	\$ 1,170.00
☐ Yes ☐ No		AND INSTALL HYDRAULIC TANK					\$ 1,170.00
	Cause	and for this label				Subtotal:	\$ 1,170.00
	No cause has b	een found for this job					
0 . (AS DEMO	VE AND INTALL TRANS	MISSIO	M		Estimate	d Cost
Customer Approval		VE AND INTALL TRANS	MISSIC	114		Parts:	\$ 26,184.91
	Complaint	AND INITAL TRANSMISSION				Labor:	\$ 3,900.00
☐ Yes ☐ No	05 - REMOVE A	AND INTALL TRANSMISSION				Subtotal:	\$ 30,084.91
	- REMOVE & IN	ISTALL HYDRAULIC PUMPS				Oubtotai.	Ψ 00,001.01
	- REMOVE & IN	ISTAUL DRIVESHAFTS					
	- REMOVE & IN	ISTALL HYDRAULIC AND TRANS	OISSIME	LINES			
	Cause	/					
		en found for this job.					
	Parts				= .4		
	Part No.	Description	Qty	List	Ext		
	8015043457	HYDRAULIC PUMP	1.00	2,958.80	2,958.80		
	914515	RETAINING RING	2.00	1.94	3.88		
	9015043457	HYDRAULIC PUMP	1.00	6,488.06	6,488.06		
	925096	O-RING	2.00	4.69	9.38		
	930844	PLAIN WASHER	12.00	1.86	22.32		
	9015068648	HYDRAULIC PUMP	1.00	6,488.06	6,488.06		

2615 20th Ave Fairbanks, AK 99709 (907) 931-8808



Number Est. Date
1537494 08/07/2025
Est. Created By
Dan Kimmel
Location Customer PO
FBX

					15%		
	Part No. 8015068648 975121	Description HYDRAULIC PUMP FLANGE SCREW	Qty 1.00 12.00	List 3,062.36 5.70	Ext 3,062.36 68.40	2000	
	60110070	LOCK NUT	12.00	4.94 751.31	59.28 751.31	1	
	15131481	COUPLING KIT	1.00 1.00	4,226.77	4,226.77		
	9015068597 8015068597	HYDRAULIC PUMP HYDRAULIC PUMP	1.00	2,046.29	2,046.29		
Customer Approval		SE ENGINE REAR MA	IN SEAL	- 0		Estimated C	ost
Customer Approval	Complaint			4		Parts: Labor:	\$ 623.60 \$ 390.00
□ Yes □ No	06 - CHANGE E	NGINE REAR MAIN SEAL				Subtotal:	\$ 1,013.60
	- REMOVE AND - REMOVE, INS) INSTALL FLYWHEEL SPECT CRANKSHAFT, AND IN	NSTALL REA	R MAIN SEA	L		
		een found for this job.	1				
	Parts	and the state of t		Qty	List Ext		
	Part No. Des	cription EVE ** SUPERSEDES 154389	ne**	-	5,03 166.03		
	17460059 SLE 1543563 WAS		,0		1.44 300.16		
		DEFLECTOR RING			5.07 65.07		
				14.00	6.50 91.00		
	1677893 SCR 1556907 GAS				1.34 1.34		
Customer Approval	07 - CHANG	Estimated C	ost				
Customer Approvar	Complaint	JE MIJOO, HOULE ! O				Parts:	\$ 0.00
☐ Yes ☐ No	07 - CHANGE	ISC. HOSES FOUND DURIN	G THE JOB			Labor:	\$ 975.00
e res e no	HOSES AND S PARTS WILL N Cause	EALS ARE NOT INCLUDED AT THE SECOND S	AS WE DO N	OT KNOW W	/нісн	Subtotal:	\$ 975.00
/						Estimated C	ost
Fees						Shop Fee:	\$ 400.00
						Environmental Fee:	\$ 300.00
						Subtotal:	\$ 700.00
		Total: \$ 41	,429.02				

2615 20th Ave Fairbanks, AK 99709 (907) 931-8808



Estimate						
Number Est. Date						
1537494	08/07/2025					
Est. 0	Created By					
Da	n Kimmel					
Location	Customer PO					
FBX						
9						

** Quoted prices are valid for 30 days, but are subject to change due to ongoing uncertainties about the impact of tariffs. Fluctuations in costs beyond our control may require adjustments. We are committed to providing transparent communication and competitive pricing. ** This is a preliminary estimate. Additional charges to the estimate may be required for the actual repair. Customer is responsible for payment in full to Construction Machinery Industrial, LLC regardless of insurance coverage or reimbursement. TERMS: NET CASH or ACCOUNT. **2.5% surcharge on all VISA and MASTERCARD payments** Terms: Net 30 days; except for equipment invoices, which are due upon receipt. Returns: Authorized within 30 days of invoice date, with a minimum of 15% restocking charge plus return freight. Non-Returnable items include; hoses, gaskets, seals, electrical, & opened kits. Service charge of 1% per month assessed on all past due accounts.

Authorized Signer:		Date:
	1	
	f	
	<i>j</i>	
	A Committee of the Comm	
	and the second s	
, in the state of		
1		
A STATE OF THE STA		

2615 20th Ave Fairbanks, AK 99709 (907) 931-8808



Estimate

Number Est. Date

1537494 08/19/2025

Est. Created By

Dan Kimmel


Location Customer PO

FBX

		L.	FBX	
	Bill To		Machine	
CITY OF DELTA JUNCTION [440074] P O BOX 229 DELTA JUNCTION, AK 99737		Stock #: RT1554 Make/Model: VOLVO L220F S/N: L220FT00008248 Sold on 2/28/2011 Description: VOLVO L220F LOAL Total hours as of 08/19/2025: 380		
		Notes		
REV/CITY of DELTA RT15: LOCATION: CMI SHOP	54 - HYD OIL OVERFILLING TF	RANSMISSION		
		Jobs		
Customer Approval	ANALYSIS FORM (JH Complaint Technicians assigned to this w Associated with the make and commencing any work the tec concerns and recommended p with the work to be performed.	work order must have a copy of the Service Ma model of the equipment to be worked on. Prion hnician will have read and understood safety procedures by manufacturer for the tasks asso to (JHA) required for the tasks on this WO?	Parts: Labor: Subtotal:	\$ 0.00 \$ 0.00 \$ 0.00
Customer Approval	01 - WASH MACHINE		Estimat	ed Cost
	Complaint		Parts:	\$ 0.00
□ Yes □ No	CUSTOMER STATES HYD FLUID IS OVERFILLING THE TRANSMISSION & FILLING THE ENGINE Cause No cause has been found for this job.			\$ 975.00 \$ 975.00
Customer Approval	02 - TROUBLESHOO	FENGINE OIL OVER FULL	Estimat	ed Cost
	Complaint		Parts:	\$ 0.00
□ Yes □ No	08 - TROUBLESHOOT ENGIN	NE OVER FILL	Labor:	\$ 780.00
	Cause No cause has been found for t	his job.	Subtotal:	\$ 780.00
Customer Approval	03 - DRAIN FLUIDS		Estimate	ed Cost
	Complaint		Parts:	\$ 3,585.51

2615 20th Ave Fairbanks, AK 99709 (907) 931-8808





☐ Yes ☐ No	02 - CHANGE F	ILTERS, DRAIN & REFILL FLU	JIDS			Labor:	\$ 585.00
	- ENGINE OIL						\$ 4,170.51
	- TRANSMISSIO	ON OIL					
	- HYDRAULIC C	DIL					
	Cause						
		een found for this job.					
	Parts	B 1.41					
	Part No.	Description	Qty	List	Ext		
	11038369	GASKET	1.00	19.36	19.36		
	11172907 11707077	AIR FILTER	1.00	42.59	42.59		
	17418113	FILTER INSERT	1.00	33.69	33.69		
	17418113	FILTER CARTRIDGE FILTER ELEMENT	1.00	144.31	144.31		
	21707132	OIL FILTER	1.00 1.00	136.46	136.46		
	Oil & Grease	AT102 15 GAL	1.00	32.14	32.14		
	Oil & Grease	15-40 12 GAL	1.00	559.20 268.68	559.20 268.68		
	Oil & Grease	HYD. OIL 70 GAL	1.00	2,284.80	2,284.80		
	17533661	OIL FILTER	2.00	32.14	64.28		
	17000001	OILT ILTER	2.00	32.14	04.20		
Customer Approval	04 - REMOV	E AND INSTALL CAB				Estimated	d Cost
	Complaint					Parts:	\$ 0.00
□ Yes □ No	1	ND INSTALL CAB				Labor:	\$ 2,340.00
	Cause	and forward from the Co. Co.				Subtotal:	\$ 2,340.00
	No cause has be	en found for this job.					
Customer Approval	05 - REMOV	E AND INSTALL HYD	RAULIC '	TANK		Estimated Cost	
	Complaint					Parts:	\$ 0.00
□ Yes □ No	04 - REMOVE AI	ND INSTALL HYDRAULIC TAN	١K			Labor:	\$ 1,170.00
	Cause					Subtotal:	\$ 1,170.00
	No cause has be	en found for this job.					
Customer Approval	06 - REMOV	E AND INTALL TRANS	SMISSIO	N		Estimated	l Cost
	Complaint					Parts:	\$ 0.00
☐ Yes ☐ No		ND INTALL TRANSMISSION				Labor:	\$ 3,900.00
	DEL403 = 5					Subtotal:	\$ 3,900.00
		STALL HYDRAULIC PUMPS STALL DRIVESHAFTS					
		STALL DRIVESHAFTS STALL HYDRAULIC AND TRAN	NOISSIME	LINES			
	Cause		.5551014				
		en found for this job.					
		-					

2615 20th Ave Fairbanks, AK 99709 (907) 931-8808



Estimate

Number Est. Date

1537494 08/19/2025

Est. Created By

Dan Kimmel


Location Customer PO

FBX

Customer Approval	07 - CHA	NGE ENGINE REAR MAIN SEAL	,			Estimated	
	Complain	t				Parts:	\$ 623.60
☐ Yes ☐ No	06 - CHANG	E ENGINE REAR MAIN SEAL				Labor:	\$ 390.00
						Subtotal:	\$ 1,013.60
		AND INSTALL FLYWHEEL INSPECT CRANKSHAFT, AND INSTALL REA	ΔΡ ΜΔΙΙ	V SEAL			
	Cause	INSPECT CRAINCHAFT, AND INSTALL ILL	rai v iviraii	TOLAL			
		s been found for this job.					
	Parts						
	Part No. D	escription	C	ty Li	st Ext		
	1556907		1.	00 1.3	34 1.34		
	1677893 S	CREW	14.	00 6.5	91.00		
	17460059 S	LEEVE ** SUPERSEDES 1543896**	1.	00 166.0	3 166.03		
	15004855 C	OIL DEFLECTOR RING	1.	00 65.0	7 65.07		
	1543563 V	VASHER	14.	00 21.4	4 300.16		
	00 0114	NOT OUTTOWED ARREDVED D	IMPC	шое	Ee	Estimated	d Cost
Customer Approval		NGE CUSTOMER APPROVED P				Parts:	\$ 27,386.18
5.V 5.N	AND OTI	HER PARTS FOUND FAULTY DU	KING	IHE	IEAK	Labor:	\$ 975.00
☐ Yes ☐ No	DOWN.					Subtotal:	\$ 28,361.18
	Complain					Oubtotal.	Ψ 20,001.10
		, PUMPS, SEALS, AND OTHER PARTS TO					
	CUSTOMER	BEFORE REPAIRS CAN BE MADE AFTER	DISAS	SEMBL	1		
	- THIS SEGI	MENT SHOWS THE RECOMMEND PARTS T	O BE C	HANGE	D		
		IS REPAIR, THE LABOR HOURS WILL VAR'					
	WHICH PAR	RTS THE CUSTOMER DECIDES TO CHANG	E.				
	Cause						
		s been found for this job.					
	Parts		06.	1:-4	Ext		
	Part No.	Description	Qty	List 751.31			
	15131481	COUPLING KIT		244.85			
	17458350	PISTON SEAL **SS PN:#17272888** PISTON SEAL ** SS:PN#17279240**			244.85		
	17458353		12.00	4.94			
		LOCK NUT			3,282.38		
		HYDRAULIC PUMP			2,138.37		
		HYDRAULIC PUMP HYDRAULIC PUMP			3,282.38		
		HYDRAULIC PUMP **Available in Byhalia**		•	6,488.06		
		HYDRAULIC PUMP			4,226.77		
		HYDRAULIC PUMP **Available in Reno**			6,488.06		
	914515	RETAINING RING **Available in Reno**	2.00	1.94			
	925096	O-RING **CMI ANC**	2.00	4.69			
	323030	O-IMING OWILAND	2.00		0.00	l)	

2615 20th Ave Fairbanks, AK 99709 (907) 931-8808





	Part No.	Description	Qty	List	Ext		
	926254	O-RING	2.00	28.53	57.06		
	930844	PLAIN WASHER	12.00	1.86	22.32		
	968207	O-RING **CMI ANC**	1.00	18.83	18.83		
	975121	FLANGE SCREW	12.00	5.70	68,40		
	NOTE	NEXT DAY AIR - \$963.30 LTL - \$210.72 STOCK ORDER	1.00	0.00	0.00		
Fees	-					Estimated Co	ost
						Shop Fee:	\$ 400.00
						Environmental Fee:	\$ 300.00
						Subtotal:	\$ 700.00

** Quoted prices are valid for 30 days, but are subject to change due to ongoing uncertainties about the impact of tariffs. Fluctuations in costs beyond our control may require adjustments. We are committed to providing transparent communication and competitive pricing. ** This is a preliminary estimate. Additional charges to the estimate may be required for the actual repair. Customer is responsible for payment in full to Construction Machinery Industrial, LLC regardless of insurance coverage or reimbursement. TERMS: NET CASH or ACCOUNT. **2.5% surcharge on all VISA and MASTERCARD payments** Terms: Net 30 days; except for equipment invoices, which are due upon receipt. Returns: Authorized within 30 days of invoice date, with a minimum of 15% restocking charge plus return freight. Non-Returnable items include; hoses, gaskets, seals, electrical, & opened kits. Service charge of 1% per month assessed on all past due accounts.

Authorized Signer:	Date	e:

Deltas East Side Auto LLC

2250 Mil Tan Road Delta Junction, AK. 99737 Phone: 907-750-2303 Fax: - - 004655

Estimate Date: 8/19/2025

Estimate for Services

City Of Delta Junction - Delta Junction City Of

0 -Lic#: -

Odom. In: 0

VIN#:

Part Description / Number	Qty	Sale	Ext	Labor Description	Extended
CHV RANDO HDZ ISO 32 1/55	1.00	2,313.05	2,313.05	Volvo Loader Repair	10,000.00
273260981			200 0000	Shipping-Shipping States To Dealer	977.45
Volvo Hydraulic Oil	3.00	198.58	595.74	Onlyping States to Dealer	
54025104					
Air Fitter	1.00	59.65	59,65		
11172907					
Gasket	1.00	27.11	27.11		
11038369					
Filter Cartridge	1.00	202.11	202.11		
17418113					
Oil Filter	1.00	45.01	45.01		
21707132					
Transmission Oil	3.00	234.99	704.97		
54022268					
Volvo Engine Oil	3.00	172.93	518.79		
54022803					
Filter Insert	1.00	47.18	47.18		
11707077					
Filter Element	1.00	191.11	191.11		
17438620					
Retaining Ring	2.00	2.72	5.44		
914515			40.000.00		
Hydraulic Pump	1.0013	,683.50	13,683.50		
9015043457			40.4		
ORing	2.00	6.57	13.14		
925096	40.00		24.22		
Plain Washer	12.00	2.60	31.20		
930844	4.000	000 50	40,000,50		
Hydraulic Pump	1.0013,	683.50	13,683.50		
90150686498	40.00	0.00	20.01		
Lock Nut	12.00	6.92	83.04		
60110070			4.000.0		
Coupling Kit	1.00 1,	052.21	1,052.21		
15131481					
Hydraulic Pump	1.00 8,9	914.38	8,914.38		
9015068597					
Sleeve	1.00 2	232.53	232.53		
17460059					
Vasher	14.00	30.03	420.42		
1543563					
Dil Deflector Ring	1.00	91.13	91.13		
15004855					
Shahata			Page 1 of 2	Comment to cope as	
itong, Elisheba			Page 1 of 2	Copyright (c) 2025 Mitchell Repair Information	Company, LLC esthrs 4.06.2016u